

Prairie Blaster SLA Battery Kit

Please charge the battery before installation. Connect the charger to the battery harness. See figure 1. The charger LED will turn to green when charging is complete.

Connect the SLA battery harness to the Prairie Blaster battery connector. Carefully work the excess wire into the slot in the battery well. Position the battery in the well as shown in figure 2. Replace the battery door.



Figure 1



Figure 2

Always charge the battery after use, and before long storage periods.

Do not allow the battery to remain connected to the charger for extended time periods. Maximum charge time is 8 hours.

FOXPRO INC 14 Fox Hollow Drive Lewistown, PA 17044
(717) 248-2507 www.gofoxpro.com

11/09